

Inspection Photos

07/18/2024

Operator: WINDSOR ENERGY GROUP LLC

#10081

Location ID: 397591

Inspection Doc: 696206001

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC #10081

Location ID: 397591



Photo 1: Photos taken from the east end of the Location, facing southwest and northwest. Location is not progressing towards 1004 uniform, perennial vegetative requirements; vegetation is predominantly undesirable plant species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC #10081

Location ID: 397591




Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC #10081

Location ID: 397591



Photo 3: Photo shows reclamation work including, but not limited to, removal of culvert/gravel, compaction alleviation, recontouring/regrading and revegetation activities have not been performed at the access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources