

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/13NWNW

Location ID: 312601

Date: 7/2/2024



Entrance to location - Photo #03224



Well head and Pump jack - Photo #03231

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/13NWNW

Location ID: 312601

Date: 7/2/2024



Separator and meter run - Photo #03238




Tank battery/weeds - Photo #03243

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/13NWNW

Location ID: 312601

Date: 7/2/2024



Inaccurate operator information on battery sign - Photo #03244



Tank label missing volume capacity/inaccurate operator information - Photo #03245

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/13NWNW

Location ID: 312601

Date: 7/2/2024



Debris - Photo #03255



Unused equipment - Photo #03257

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/13NWNW

Location ID: 312601

Date: 7/2/2024



Storage of supplies/equipment - Photo #03258



Storage of supplies/equipment - Photo #03260

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/13NWNW

Location ID: 312601

Date: 7/2/2024



Unused equipment - Photo #03262



Unused equipment - Photo #03264

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/13NWNW

Location ID: 312601

Date: 7/2/2024



Northeast corner of location - Photo #03251



Southeast corner of location - Photo #03252