

Inspection Photos

Location: Caerus Piceance LLC Colohan-67S96W/34NWSW

Location ID: 334075

Date: 7/9/2024



Entrance to location - Photo #03436

Location - Photo #03444

Inspection Photos

Location: Caerus Piceance LLC Colohan-67S96W/34NWSW

Location ID: 334075

Date: 7/9/2024



Wellhead/Chemical tank - Photo #03437



Separators - Photo #03440

Inspection Photos

Location: Caerus Piceance LLC Colohan-67S96W/34NWSW

Location ID: 334075

Date: 7/9/2024



Tank battery - Photo #03443



Signage has not been posted at northwest corner of location at tank battery - Photo #03448

Inspection Photos

Location: Caerus Piceance LLC Colohan-67S96W/34NWSW

Location ID: 334075

Date: 7/9/2024



Separator/Pig station - Photo #03450



Northeast corner of location - Photo #03454

Inspection Photos

Location: Caerus Piceance LLC Colohan-67S96W/34NWSW

Location ID: 334075

Date: 7/9/2024



Southeast corner of location - Photo #03455



Debris - Photo #03456

Inspection Photos

Location: Caerus Piceance LLC Colohan-67S96W/34NWSW

Location ID: 334075

Date: 7/9/2024



Debris - Photo #03458



Debris - Photo #03459