

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/21SWNE

Location ID: 324467

Date: 7/10/2024



Entrance to location - Photo #03470



Location - Photo #03493

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/21SWNE

Location ID: 324467

Date: 7/10/2024



Wellhead - Photo #03471



Separator - Photo #03483

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/21SWNE

Location ID: 324467

Date: 7/10/2024



Tank battery - Photo #03492



Southeast corner of location - Photo #03496

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/21SWNE

Location ID: 324467

Date: 7/10/2024



Northeast corner of location - Photo #03497



Tracking pad - Photo #03498

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/21SWNE

Location ID: 324467

Date: 7/10/2024



Stained soils and gravel - Photo #03472

Stained soils and gravel - Photo #03473

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/21SWNE

Location ID: 324467

Date: 7/10/2024



Stained soils and gravel - Photo #03474



Stained soils and gravel - Photo #03476

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/21SWNE

Location ID: 324467

Date: 7/10/2024



Debris - Photo #03478

Debris - Photo #03479

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/21SWNE

Location ID: 324467

Date: 7/10/2024



Debris - Photo #03480

Debris - Photo #03482

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/21SWNE

Location ID: 324467

Date: 7/10/2024



Open ended piping/wildlife hazard - Photo #03484

Open ended piping/wildlife hazard - Photo #03486

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/21SWNE

Location ID: 324467

Date: 7/10/2024



Debris - Photo #03488

Debris - Photo #03489

Inspection Photos

Location: Gunnison Energy LLC Federal -610S90W/21SWNE

Location ID: 324467

Date: 7/10/2024



Debris - Photo #03491