

Inspection Photos

Location: Laramie Energy LLC Kimball Creek Pad/23-4C-995

Location ID: 420164

Date: 7/19/2024



Entrance to location - Photo #03547



Location - Photo #03555

Inspection Photos

Location: Laramie Energy LLC Kimball Creek Pad/23-4C-995

Location ID: 420164

Date: 7/19/2024



Wellheads/Chemical tank - Photo #03548



Separators/Methanol tank - Photo #03550

Inspection Photos

Location: Laramie Energy LLC Kimball Creek Pad/23-4C-995

Location ID: 420164

Date: 7/19/2024



Tank battery - Photo #03554



Northeast corner of location - Photo #03563

Inspection Photos

Location: Laramie Energy LLC Kimball Creek Pad/23-4C-995

Location ID: 420164

Date: 7/19/2024



Southeast corner of location - Photo #03564



Northwest corner of location - Photo #03567

Inspection Photos

Location: Laramie Energy LLC Kimball Creek Pad/23-4C-995

Location ID: 420164

Date: 7/19/2024



Open ended load line - Photo #03560

Open ended load line - Photo #03561

Inspection Photos

Location: Laramie Energy LLC Kimball Creek Pad/23-4C-995

Location ID: 420164

Date: 7/19/2024



Open ended load line - Photo #03562



Illegible label - Photo #03553