

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/35C-795

Location ID: 334087

Date: 7/17/2024



Jul 17, 2024 at 12:19:26
Parachute CO 81635
United States



Jul 17, 2024 at 12:19:51
Parachute CO 81635
United States

Location Entrance – Photo #02294

Wellheads – Photo #02295

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/35C-795

Location ID: 334087

Date: 7/17/2024



Separators – Photo #02297



Tank Battery – Photo #02298

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/35C-795

Location ID: 334087

Date: 7/17/2024



Damaged Berm from Destabilized Cut Slope – Photo #02299



Damaged Berm from Destabilized Cut Slope – Photo #02300

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/35C-795

Location ID: 334087

Date: 7/17/2024



Damaged Berm from Destabilized Cut Slope – Photo #02301