

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/35L-795 Pad

Location ID: 416986

Date: 7/17/2024



Wellheads – Photo #02308



Separator/Unsecured Hatch – Photo #02305

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/35L-795 Pad

Location ID: 416986

Date: 7/17/2024



Separator/Unsecured Hatch – Photo #02306



Tank Battery – Photo #02304