

Operator: BCEI
Location Name: Antelope 18C
Loc ID: 418098
Inspection: 696306501



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: All 4 remaining Wellhead Signs have faded no longer visible; see photos. Install sign to comply with Rule 605.d

CA Resolution: Operator has reported that the identified Wellhead signs have now been appropriately replaced/installed to comply with Rule 605.d.