

Operator: BCEI

Location Name: ANTELOPE 23-19 Pad

Loc ID: 420769

Inspection: 696306490



Exhibit A



Exhibit B

CA: All 4 remaining Wellhead Signs have faded no longer visible; see photos. Install sign to comply with Rule 605.d

CA Resolution: Operator has reported that the identified Wellhead signs have now been appropriately replaced/installed to comply with Rule 605.d.