

Operator: HPR

Location Name: Anschutz Equus Farms 4-62-33 NWNW

Loc ID: 437854

Inspection: 713900536



Exhibit A



Exhibit B



Exhibit C

CA: Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. Vegetation throughout the interim areas has not met Rule 1003 standards and will remain IN-PROCESS. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. ECMC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.

CA Resolution: Operator has provided photo documentation to show that weeds and undesirable vegetation have been addressed. The area has been reseeded, and straw crimped to provide stabilization and promote more uniform future growth. Location currently complies with Rule 1003.