

Operator: XOG

Location Name: Hippen UU 32-2,13; Pezoldt UU 32-4J

Loc ID: 463225

Inspection: 713900721



Exhibit A



Exhibit B

CA: This location does not comply with Rule 1004. Weedy, annual vegetation was observed which includes but not limited to cheatgrass and kochia. A List B CO Noxious weed, Field bindweed, was observed and flowering at the location. Bare soil also dominates the tank battery location area. Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management. There is no corrective action date due to this being out of compliance. Final reclamation activities shall be complete as soon as environmental conditions permit.

CA Resolution: Operator has provided photo documentation to show that the location has been mowed to maintain area and address undesirable vegetation. Operator also noted that during the mowing process, a bagging attachment was utilized to collect developed seed heads. Seeding of the location is planned for late summer/early Fall when temperatures are lower and moisture is more consistent.