

Final Reclamation and Stormwater Inspection

Date: 07/23/2024

Operator: PDC ENERGY INC - 69175

Location ID: 445423

Inspection Document #: 708201423

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Yaklich 5-11
Location ID: 445423



Photo 1. All trash previously documented has been removed from the location.

Inspection Photos
Location Name: Yaklich 5-11
Location ID: 445423



Photo 2. Taken from the western portion of the former tank battery location. It appears that the Operator has performed additional reclamation work with evidence of drill rows and straw crimped mulch. This location will be inspected at a later date to verify compliance with Rule 1004.

Inspection Photos
Location Name: Yaklich 5-11
Location ID: 445423



Photo 3. Taken from the southern portion of the former tank battery location. See comments in Photo 2.