

Final Reclamation and Stormwater Inspection

Date: 07/23/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 305348

Inspection Document #: 708201428

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Howard A 27-9
Location ID: 305348



Photo 1. Facing north. The former well location has subsided approximately 1-1.5' bsg. Additional reclamation activities are required to restore grade in order to match the adjacent topography.

Inspection Photos
Location Name: Howard A 27-9
Location ID: 305348



Photo 2. Facing east; see comments in Photo 1.

Inspection Photos
Location Name: Howard A 27-9
Location ID: 305348



Photo 3. Facing south; see comments in Photo 1.

Inspection Photos
Location Name: Howard A 27-9
Location ID: 305348



Photo 4. Facing west; see comments in Photo 1.