

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/27/2024

Submitted Date:

07/25/2024

Document Number:

714300104

FIELD INSPECTION FORM

Loc ID 336456 Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
 Address: 555 17TH STREET SUITE 3700
 City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Evans, Jacob		jevans@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486884	SPILL OR RELEASE	CL	05/03/2024		-	Wandell 33-7, 43-7, 32-7	EI

General Comment:

This is an environmental inspection to determine progress on Spill ID 486884(CL)/Remediation Project No 31476. Inspection submitted to document site conditions at the time of inspection.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Inspected Facilities

Facility ID: 486884 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Spill excavation has been backfilled; no soil has been stockpiled on location.

Corrective Action: Operator shall provide an updated Form 27 for Remediation #31476 with a workplan and timeline for remediation of Spill ID 486884. Date: 08/08/2024

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714300105	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6638799