

# Inspection Photos

July 9th, 2024

Operator: Kinder Morgan CO2 CO - 46685

Location ID: 313533

Inspection Document #: 714000979

Montezuma County, CO

Township: NWSW 31 37N 17W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: McElmo Dome Unit MC 4  
Location ID: 313533



**Photo 1.** View of the shut in well taken from the western edge facing center. Note: inspection took place during remediation efforts, soil/material removed from around shut it well.



API #: 083-06437

Inspection Photos  
Location Name: McElmo Dome Unit MC 4  
Location ID: 313533



**Photo 2.** View of removed material from around well head stored on location.  
Note: if soil is contaminated additional BMPs need to be installed during the storing process.