

Inspection Photos

July 24th, 2024

Operator: SG Interstes LTD - 77330

Location ID: 385883

Inspection Document #: 714000980

La Plata County, CO

Township: SWNW 17 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Short 33-9 17-1
Location ID: 385883

7/24/24
+37.118675,-107.848412
221° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the disturbance taken from the northern edge facing center. Note: location is abandoned but location has been constructed, cut slopes are evident.

API #: 067-08146

Inspection Photos
Location Name: Short 33-9 17-1
Location ID: 385883

7/24/24
+37.106435,-107.854137
217° SW



Photo 2. View of the western cut slope that remains unreclaimed/contoured.

Inspection Photos
Location Name: Short 33-9 17-1
Location ID: 385883



7/24/24
+37.106241,-107.854212
117° SE