

Inspection Photos

July 24th, 2024

Operator: Elm Ridge Exploration Company - 26625

Location ID: 325440

Inspection Document #: 714000981

La Plata County, CO

Township: NWSW 17 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ute 2
Location ID: 325440

7/24/24
+37.102164,-107.855736
31° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area taken from the southern edge facing center.

API #: 067-06381

Inspection Photos
Location Name: Ute 2
Location ID: 325440





Photo 2. Cardinal photos taken from the center of the disturbance, left photo facing north, right photo facing east.

Inspection Photos
Location Name: Ute 2
Location ID: 325440



Photo 3. Cardinal photos taken from the center of the disturbance, left photo facing south, right photo facing west.

Inspection Photos
Location Name: Ute 2
Location ID: 325440



Photo 4. Large patches of Russian knapweed and Musk thistle observed flowering on location.

Inspection Photos
Location Name: Ute 2
Location ID: 325440



Photo 5. Reference area comprised of Smooth brome, Rabbitbrush and Juniper.