

**Inspection Photos**  
**Operator: Citation**  
**Location Name: Tuttle 33-35**  
**API: 05-061-06621**



**Wellhead location. Meter shed belongs to the gas company**



**Inspection Photos**  
**Operator: Citation**  
**Location Name: Tuttle 33-35**  
**API: 05-061-06621**



**Location of where the tank battery was. Some debris laying around needs picked up**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Operator: Citation**  
**Location Name: Tuttle 33-35**  
**API: 05-061-06621**



**Location of where the treater was**

