

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403853582

Date Received:  
07/13/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

-

[rbucogccinspectionreports@chevron.onmicrosoft.com](mailto:rbucogccinspectionreports@chevron.onmicrosoft.com)

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714201156

Inspection Date: 06/18/2024

FIR Submit Date: 06/18/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 438174

Location Name: Coalview Number: G02-64-1HN County: \_\_\_\_\_  
Pad

Qtrqr: NESE Sec: 1 Twp: 4N Range: 65W Meridian: 6

Latitude: 40.337600 Longitude: -104.603300

### FACILITY - API Number: 05-123-00 Facility ID: 438174

Facility Name: Coalview Number: G02-64-1HN  
Pad

Qtrqr: NESE Sec: 1 Twp: 4N Range: 65W Meridian: 6

Latitude: 40.337600 Longitude: -104.603300

### CORRECTIVE ACTIONS:

1 ☒ CA# 195975

Corrective Action: Comply with Rule 606.

Date: 08/18/2024

Response: CA COMPLETED

Date of Completion: 07/12/2024

Operator Comment: Gas meter is connected to live sources, has pressure and is locked in the "off" position on the upstream side. Complying with Rule 606.

ECMC Decision: Approved via an AMI



Comply with 1002.f.(D).

Date: 08/18/2024

CA COMPLETED

Date of Completion: 07/12/2024

Complied with Rule 1002.f.(D)

Approved via an AMI

### OPERATOR COMMENT AND SUBMITTAL

Removed doors on sound wall that were in disrepair, gas meter in question is connected to active sources of pressure on a live system. Locked "off" on the upstream side. See photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Jeff White

Signed:

HSE

Date: 7/13/2024 4:20:12 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403853582	FIR RESOLUTION SUBMITTED
403853583	photos

Total Attach: 2 Files