

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/34NENE

Location ID: 335378

Date: 7/18/2024



North End of Location – Photo #02358



Wellheads – Photo #02361

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/34NENE

Location ID: 335378

Date: 7/18/2024



Separators – Photo #02359



Tank Battery – Photo #02360