

Inspection Photos  
Location Name: Hodgson 19-1  
Location ID: 321336



Photo 1 well head and equipment

Photo 2 tank battery and production equipment

Inspection Photos  
Location Name: Hodgson 19-1  
Location ID: 321336



Photo 3 tank battery



Photo 4 production equipment