

Inspection Photos

API: 071-09127

Operator: OGRIS OPERATING LLC

Inspection Date: 7/22/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. There is a culvert in the canyon bottom that needs to be cleaned out.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing west toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources