

Inspection Photos
Location Name: Red Lady 6-64 4-6 2HN
Location ID: 484179



Pic 1 Cementing equipment



Pic 2 Cementing equipment

Inspection Photos
Location Name: Red Lady 6-64 4-6 2HN
Location ID: 484179

Jul 18, 2024 at 10:46:46 AM
39.561702,-104.550968
Elbert County
ECMC



Pic 3 Chemical storage