

Inspection Photos
Location: Cosslett 3
Facility ID: 474780



Photo 1 – Excavation



Photo 2 – Fencing around excavation and weeds



Inspection Photos
Location
Facility ID:



Photo 3 – Trash



Photo 4 – Trash in excavation



Inspection Photos
Location
Facility ID:



Photo 5 –



Photo 6 –



Inspection Photos

Location

Facility ID:



Photo 7 – Torn fencing around excavation



Photo 8 – Torn fencing around excavation



Inspection Photos

Location

Facility ID:



Photo 9 –



Photo 10 – Torn fencing to prevent site access



Inspection Photos

Location

Facility ID:



Photo 11 – Torn fencing to prevent site access



Photo 12 – Torn fencing to prevent site access



Inspection Photos

Location

Facility ID:



Photo 13 – Tracking issues




Photo 14 – Torn fencing to prevent site access



Inspection Photos

Location

Facility ID:



Photo 15 – Torn fencing to prevent site access



Photo 16 –



Inspection Photos

Location

Facility ID:



Photo 17 – Site access

