

Inspection Photos

July 24th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 333489

Inspection Document #: 714000989

La Plata County, CO

Township: NWSE 17 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Southern Ute 33-9 17-2
Location ID: 333489

7/24/24
+37.100248,-107.844756
296° NW



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos

Location Name: Southern Ute 33-9 17-2

Location ID: 333489



Inspection Photos
Location Name: Southern Ute 33-9 17-2
Location ID: 333489



7/24/24
+37.100250,-107.845090
139° SE

Photo 3. View of the eastern interim reclamation area facing southeast.