

Inspection Photos

July 24th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 325127

Inspection Document #: 714000993

La Plata County, CO

Township: SWNW 23 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McCarville 1
Location ID: 325127



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: McCarville 1
Location ID: 325127



Photo 2. View of unmarked guy line anchors on location.

Inspection Photos
Location Name: McCarville 1
Location ID: 325127




Photo 3. View of storm water and sediment transport at well disturbance and along access road.

Inspection Photos
Location Name: McCarville 1
Location ID: 325127



7/24/24
+37.092693,-107.801334
245° SW

Photo 4. View of sediment deposition occurring at the well disturbance access point.