

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/27SWSE

Location ID: 335220

Date: 7/25/2024



Location Entrance – Photo #02414



Wellheads – Photo #02415



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/27SWSE

Location ID: 335220

Date: 7/25/2024



Separators – Photo #02418



Tank Battery – Photo #02417