





| <b>SITE NAME:</b> Miller 29N 18N 4N-24HZ O SA            |                       |                 |             |           |        |                     | <b>DATE:</b><br>5/29/2024                  | <b>REM. PROJECT #:</b> | <b>WEATHER:</b><br>Sunny, 60 F |
|--|-----------------------|-----------------|-------------|-----------|--------|---------------------|--|------------------------|--------------------------------|
| <b>SITE DIRECTIONS:</b> Cr 32 & Cr 35, E 0.1, S 0.2 into |                       |                 |             |           |        |                     | <b>CLIENT:</b> OXY                         |                        |                                |
| <b>LEGALS AND LAT/LONG:</b> 40.204306,-104.725920        |                       |                 |             |           |        |                     | <b>TASMAN PERSONNEL:</b> PD                |                        |                                |
| <b>SOIL TYPES:</b> Silty Sand - SM                       |                       |                 |             |           |        |                     | <b>SURFACE GRADIENT:</b> West              |                        |                                |
| SOIL SAMPLING  |                       |                 |             |           |        |                     | FACILITY INFRASTRUCTURE                    |                        |                                |
| Date/Time  | Soil Sample ID        | PID (ppm)       | Visual      | Olfactory | Photo? | Grab or Lab Sample? | EQUIPMENT                                  | Quantity               |                                |
| 6/6/2024 11:00   | REL-B02@4'            | 5.2             | No Staining | No Odor   | Yes    | Lab                 | Above Ground Storage Tank (AST)            |                        |                                |
| 6/6/2024 11:02   | REL-N01@3'            | 1.9             | No Staining | No Odor   | Yes    | Lab                 | Buried or Partially Buried Vessel          |                        |                                |
| 6/6/2024 11:04   | REL-S01@3'            | 1.6             | No Staining | No Odor   | Yes    | Lab                 | Separator                                  |                        |                                |
| 6/6/2024 11:06   | REL-E01@3'            | 1.7             | No Staining | No Odor   | Yes    | Lab                 | Emission Control Device (ECD)              |                        |                                |
| 6/6/2024 11:08   | REL-W01@3'            | 2.5             | No Staining | No Odor   | Yes    | Lab                 | Dump Line                                  |                        |                                |
|  |                       |                 |             |           |        |                     | Wellhead                                   |                        |                                |
|  |                       |                 |             |           |        |                     | Flowline                                   |                        |                                |
|  |                       |                 |             |           |        |                     | Other:                                     |                        |                                |
|  |                       |                 |             |           |        |                     | Soil Loads Removed                         |                        |                                |
|  |                       |                 |             |           |        |                     | IMPACTED SOIL IDENTIFIED?                  |                        |                                |
|  |                       |                 |             |           |        |                     | ESTIMATED VOLUME OF IMPACTS:               |                        |                                |
|  |                       |                 |             |           |        |                     | Date                                       | Number                 | CY                             |
|  |                       |                 |             |           |        |                     |  |                        |                                |
|  |                       |                 |             |           |        |                     |  |                        |                                |
|  |                       |                 |             |           |        |                     |  |                        |                                |
|  |                       |                 |             |           |        |                     |  |                        |                                |
|  |                       |                 |             |           |        |                     |  |                        |                                |
|  |                       |                 |             |           |        |                     | Total Removed                              | 0                      | 0                              |
|  |                       |                 |             |           |        |                     | Disposal Facility:                         |                        |                                |
|  |                       |                 |             |           |        |                     | Groundwater Recovery                       |                        |                                |
|  |                       |                 |             |           |        |                     | DATE GW ENCOUNTERED:                       | DEPTH:                 |                                |
|  |                       |                 |             |           |        |                     | GROUNDWATER IN CONTACT WITH IMPACTED SOIL? |                        |                                |
|  |                       |                 |             |           |        |                     |  |                        |                                |
|  |                       |                 |             |           |        |                     | LNAPL OR SHEEN OBSERVED ON GW?             |                        |                                |
|  |                       |                 |             |           |        |                     |  |                        |                                |
| GROUNDWATER SAMPLING                                     |                       |                 |             |           |        |                     | Date                                       | BBLs                   |                                |
| Date/Time  | Groundwater Sample ID | Depth Collected | Turbid?     | Sheen?    | Odor?  | Photo?              |  |                        |                                |
|  |                       |                 |             |           |        |                     |  |                        |                                |
|  |                       |                 |             |           |        |                     |  |                        |                                |
|  |                       |                 |             |           |        |                     | Total Removed                              | 0                      |                                |
|  |                       |                 |             |           |        |                     | Disposal Facility:                         |                        |                                |



Photographic Log



|                          |                |                        |  |
|--------------------------|----------------|------------------------|--|
| <b>Equipment ID:</b>     |                | <b>Equipment Type:</b> |  |
| <b>Material:</b>         | <b>Volume:</b> | <b>Contents:</b>       |  |
| <b>Notes/Conditions:</b> |                |                        |  |

|                          |                |                        |  |
|--------------------------|----------------|------------------------|--|
| <b>Equipment ID:</b>     |                | <b>Equipment Type:</b> |  |
| <b>Material:</b>         | <b>Volume:</b> | <b>Contents:</b>       |  |
| <b>Notes/Conditions:</b> |                |                        |  |

Photographic Log



BG-02@3"




BG-03@3"

|                          |                |                        |  |                          |                |                        |  |
|--------------------------|----------------|------------------------|--|--------------------------|----------------|------------------------|--|
| <b>Equipment ID:</b>     |                | <b>Equipment Type:</b> |  | <b>Equipment ID:</b>     |                | <b>Equipment Type:</b> |  |
| <b>Material:</b>         | <b>Volume:</b> | <b>Contents:</b>       |  | <b>Material:</b>         | <b>Volume:</b> | <b>Contents:</b>       |  |
| <b>Notes/Conditions:</b> |                |                        |  | <b>Notes/Conditions:</b> |                |                        |  |

**Photographic Log**

|   |  |                        |  |                          |  |                        |  |
|---|--|------------------------|--|--------------------------|--|------------------------|--|
|  |  |                        |  |                          |  |                        |  |
|   |  |                        |  |                          |  |                        |  |
| <b>Equipment ID:</b>  |  | <b>Equipment Type:</b> |  | <b>Equipment ID:</b>     |  | <b>Equipment Type:</b> |  |
| <b>Material:</b>  |  | <b>Volume:</b>         |  | <b>Material:</b>         |  | <b>Volume:</b>         |  |
|   |  |                        |  | <b>Contents:</b>         |  |                        |  |
| <b>Notes/Conditions:</b>  |  |                        |  | <b>Notes/Conditions:</b> |  |                        |  |
|   |  |                        |  |                          |  |                        |  |



|                          |                |                        |  |                          |                |                        |  |
|--------------------------|----------------|------------------------|--|--------------------------|----------------|------------------------|--|
| <b>Equipment ID:</b>     |                | <b>Equipment Type:</b> |  | <b>Equipment ID:</b>     |                | <b>Equipment Type:</b> |  |
| <b>Material:</b>         | <b>Volume:</b> | <b>Contents:</b>       |  | <b>Material:</b>         | <b>Volume:</b> | <b>Contents:</b>       |  |
| <b>Notes/Conditions:</b> |                |                        |  | <b>Notes/Conditions:</b> |                |                        |  |