

Inspection Photos

July 29th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325915

Inspection Document #: 714001006

La Plata County, CO

Township: SWNW 7 33N 11W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Long and Schluter 1 Menefee

Location ID: 325915



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos

Location Name: Long and Schluter 1 Menefee

Location ID: 325915



7/29/24

+37.120051,-108.088089

148° SE



Photo 2. Reference area comprised predominantly of Sagebrush.