

# Inspection Photos

July 29th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 326218

Inspection Document #: 714001008

La Plata County, CO

Township: NWSW 7 33N 11W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Long and Schluter 3 Menefee  
Location ID: 326218



7/29/24  
+37.116881,-108.090370  
243° SW



7/29/24  
+37.116869,-108.090508  
271° W

Williford Resources, L.L.C.  
Phone: 938-712-9525  
**L & S #3 Menefee**  
NW 4 - SW 4 - Sec 7 - T33N - R11W  
La Plata County, CO  
API# 05-067-07661  
Local Emergency Call 911  
Public Access Road - CR 129

Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos

Location Name: Long and Schluter 3 Menefee

Location ID: 326218



7/29/24

+37.116869,-108.090508

154° SE



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Unused equipment corrective action identified in the previous inspection doc #695108270 has been addressed/resolved.

API #: 067-07661

Inspection Photos

Location Name: Long and Schluter 3 Menefee

Location ID: 326218



7/29/24

+37.116869,-108.090508

255° W



**Photo 3.** Reference area comprised predominantly of Sagebrush.