

Inspection Photos

July 29th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325552

Inspection Document #: 714001010

La Plata County, CO

Township: SWSW 7 33N 11W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Long and Schluter 8
Location ID: 325552



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Long and Schluter 8
Location ID: 325552



Photo 2. View of the southern interim reclamation area facing southwest.

Inspection Photos
Location Name: Long and Schluter 8
Location ID: 325552



7/29/24
+37.116788,-108.089746
90° E

Photo 3. Reference area comprised predominantly of Sagebrush.