

Inspection Photos
Location Name: Amoco UPRR NOONED Price 1
Location ID: 320709

Jul 30, 2024 at 12:34:09 PM
39.724024,-103.962641
Wapahoe County
ECMC



Pic 1 tanks

Jul 30, 2024 at 12:34:23 PM
39.723945,-103.962580
Wapahoe County
ECMC



Pic 2 Separator

Inspection Photos
Location Name: Amoco UPRR NOONED Price 1
Location ID: 320709

Jul 30, 2024 at 12:34:41 PM
39.723742,-103.962491
Wapahoe County
ECMC



Pic 3 Pit

Jul 30, 2024 at 12:35:16 PM
39.723693,-103.962095
Wapahoe County
ECMC



Pic 4 pump jack / wellhead

Inspection Photos

Location Name: Amoco UPRR NOONED Price 1

Location ID: 320709



Pic 5 stained soil needs to be removed from motor house