


Operator: HPR

Location Name: Critter Creek 19-23H


Loc ID: 416812

Inspection: 668701319



☉ 79°E (T) ● 40.913795, -104.40818 ±18ft ▲ 5152ft





☀ 267°W (T) ● 40.9137, -104.40731 ±18ft ▲ 5153ft



Critter Creek 19-23H
19 Jul 2024, 10:19:41 AM

SW W NW
0 240 270 300
☼ 270°W (T) ☉ 40.9137, -104.40731 ±18ft ▲ 5153ft



Critter Creek 19-23H
19 Jul 2024, 10:18:50 AM



CA: Site located in rangeland/pasture. Poor re-vegetation. Re-vegetate with appropriate species.

CA Resolution: Operator has completed actions pertaining to restoration and revegetation of the location.