

Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 7/29/2024

Dwinell #4 wellhead.

Jul 29, 2024 1:57:43 PM
40.82457760814577N 106.2388305645436W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 7/29/2024

Dwinell #4 wellhead.

Jul 29, 2024 1:59:29 PM
40 82434689626098N 106 23861548490822W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 7/29/2024

Workover rig equipment.
Stockpiled soil on pad.

Jul 29, 2024 1:59:38 PM
40.82438256125897N 106.23865152709186W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 7/29/2024

Open excavation east of
wellhead.

Jul 29, 2024 1:58:51 PM
40.82424191292375N 106.23872956261039W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Dwinell #4

Location ID: 057-05134

Spill # 487370

Inspection Date: 7/29/2024

Looking south, photo of
Excavation

Jul 29, 2024 1:59:11 PM
40.82425653934479N 106.23867927119136W

Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 7/29/2024

A layer of shale was
observed just below the
surface in the excavation
in previous photo.

Jul 29, 2024 1:59:07 PM
40.82426077220589N 106.23867851682007W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 7/29/2024

Unused equipment.
Removed pumpjack pad.

Jul 29, 2024 1:58:24 PM
40.824397187680006N 106.23886132612824W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 7/29/2024

Former pumpjack pad.

Jul 29, 2024 1:58:43 PM
40.82425892818719N 106.23876283876598W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 7/29/2024

Second excavation west
of wellhead.

Jul 29, 2024 1:57:58 PM
40.824527903459966N 106.23882059007883W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 7/29/2024

Looking mostly east
pumpjack was PR at time
of inspection. Tubing was
stacked near the
wellhead.

Jul 29, 2024 1:58:20 PM
40.824410347267985N 106.2388588115573W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources