



Jul 8, 2024 1:02:10 PM  
+39.5768N -108.2247W

Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Spill/release area from the access road. Note the unknown tributary of Willow Creek running through the center of the photo.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Jul 8, 2024 12:45:56 PM  
+39.5769N -108.2247W

Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Spill/release area from  
the access road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Jul 8, 2024 12:58:26 PM  
+39.5769N -108.2244W

Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Point of release,  
hydrocarbon odor present  
at time of inspection.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Point of release,  
hydrocarbon odor present  
at time of inspection.

Jul 8, 2024 12:57:36 PM  
+39.5769N -108.2243W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Unknown tributary of  
Willow creek from the  
access road.

Jul 8, 2024 12:45:58 PM  
+39.5770N -108.2247W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Jul 8, 2024 12:46:45 PM  
+39.5768N -108.2246W

Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Unknown tributary of  
Willow Creek upgradient  
of the spill/release area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Unknown tributary of  
Willow Creek adjacent to  
the spill/release area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Unknown tributary of  
Willow Creek adjacent to  
the spill/release area.

Jul 8, 2024 12:49:21 PM  
+39 5768N -108 2244W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Unknown tributary of  
Willow Creek adjacent to  
the spill/release area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Unknown tributary of  
Willow Creek and Willow  
Creek confluence down  
gradient of the  
spill/release area. Note  
the dysfunctional  
absorbent boom.

Jul 8, 2024 12:52:47 PM  
+39 5765N -108.2240W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Unknown tributary of  
Willow Creek down  
gradient of the  
spill/release area. Note  
the dysfunctional  
absorbent boom.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Jul 8, 2024 12:53:42 PM  
+39.5765N -108.2240W

Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

Unknown tributary of  
Willow Creek down  
gradient of the  
spill/release area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Jul 8, 2024 12:51:51 PM  
+39.5767N -108.2242W

Inspection Photos  
Spill/Release Name: TR  
21-36-597 PW Transfer Line  
Spill/Release ID: 487252  
Inspection Date: July 8, 2024

East of the spill/release area where potentially impated material was excavated.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources