



Inspection Photos  
Location Name: WILSON CREEK  
MORRISON UNIT 20  
Location ID: 314509  
Remediation Project #: 22970  
Inspection Date: July 24, 2024

Wellhead sign.

Jul 24, 2024 10:19:11 AM  
+40.1892N -107.9212W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: WILSON CREEK  
MORRISON UNIT 20  
Location ID: 314509  
Remediation Project #: 22970  
Inspection Date: July 24, 2024

Location looking  
northwest.

Jul 24, 2024 10:19:42 AM  
+40.1891N -107.9211W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Inspection Photos**

**Location Name: WILSON CREEK**

**MORRISON UNIT 20**

**Location ID: 314509**

**Remediation Project #: 22970**

**Inspection Date: July 24, 2024**

Wellhead and unmarked riser adjacent to the wellhead.

Jul 24, 2024 10:19:49 AM  
+40.1891N -107.9211W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: WILSON CREEK  
MORRISON UNIT 20  
Location ID: 314509  
Remediation Project #: 22970  
Inspection Date: July 24, 2024

Potentially impacted  
material adjacent to the  
wellhead.

Jul 24, 2024 10:19:32 AM  
+40.1892N -107.9211W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: WILSON CREEK  
MORRISON UNIT 20  
Location ID: 314509  
Remediation Project #: 22970  
Inspection Date: July 24, 2024

Potentially impacted  
material adjacent to the  
wellhead.

Jul 24, 2024 10:19:15 AM  
+40.1892N -107.9212W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources