

**KT Resources LLC  
Ant Hill Unit County 25-12  
Location ID: 316336**



**Erosion and sediment migration**



**Erosion and sediment migration**



**KT Resources LLC  
Ant Hill Unit County 25-12  
Location ID: 316336**



**Leak and stained soil**



**Weeds**



KT Resources LLC  
Ant Hill Unit County 25-12  
Location ID: 316336



**Unsealed tank berm**



**Unsealed tank berm**

KT Resources LLC  
Ant Hill Unit County 25-12  
Location ID: 316336



**Illegible label**



**When replaced additional information is required**



KT Resources LLC  
Ant Hill Unit County 25-12  
Location ID: 316336



**Stained soil**




**Stained soil**



KT Resources LLC  
Ant Hill Unit County 25-12  
Location ID: 316336



Illegible label



Calibration overdue



**KT Resources LLC**  
**Ant Hill Unit County 25-12**  
**Location ID: 316336**



**Location from Southwest corner**



**Location from Southeast corner**



**KT Resources LLC  
Ant Hill Unit County 25-12  
Location ID: 316336**



**Location from Northeast corner**



**Location from Northwest corner**