

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Location Overview: Location is within High Priority/Density  
Habitat areas & Bald Eagle Nest/Roost sites & in close  
proximity to NSO Habitat area.**

**Section/Township/Range: 27 6S94W**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 3779 Vehicle tracks observed in ditch & some damage observed to check dams in ditch**



**Photo # 3780 Vehicle tracks observed in ditch & some damage observed to check dams in ditch**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 3781 Vehicle tracks observed in ditch & some damage observed to check dams in ditch**



**Photo # 3782 Vehicle tracks observed in ditch & some damage observed to check dams in ditch**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 3783 Vehicle tracks observed in ditch & some damage observed to check dams in ditch**



**Photo # 3784 Vehicle tracks observed in ditch & some damage observed to check dams in ditch**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 3785 Sediment trap approximately 90% full & may need maintenance in near future (N/NW area of location)**