

# Inspection Photos

Location Name: Rice 6-3 I 7 & 06-6 J I Tank Battery

Location ID: 448392



Energy & Carbon Management Commission  
40.34648, -104.93647, 1479.4m, 127°  
08/01/2024 13:31:57

**Production facility**



Energy & Carbon Management Commission  
40.34634, -104.93619, 1486.0m, 77°  
08/01/2024 13:39:57

**Battery sign**

## Inspection Photos

Location Name: Rice 6-3 I 7 & 06-6 J I Tank Battery

Location ID: 448392



Energy & Carbon Management Commission  
40.34638, -104.93623, 1487.7m, 105°  
07/16/2024 09:32:27

**Erosion damage on 7/16/2024**



Energy & Carbon Management Commission  
40.34637, -104.93626, 1479.8m, 340°  
08/01/2024 13:32:57

**Erosion damage on 8/1/2024**

**Inspection Photos**  
**Location Name: Rice 6-3 I 7 & 06-6 J I Tank Battery**  
**Location ID: 448392**



**Erosion damage on 7/16/2024**



**Erosion damage on 8/1/2024**