

Inspection Photos
Location Name: HSR Sandberg 2-6 Tank Battery
Location ID: 448393



Energy & Carbon Management Commission
40.34669, -104.92837, 1471.1m, 58°
08/01/2024 14:15:23

Production facility



Energy & Carbon Management Commission
40.34666, -104.92875, 1471.2m, 43°
08/01/2024 14:16:04

Battery sign

Inspection Photos
Location Name: HSR Sandberg 2-6 Tank Battery
Location ID: 448393



Erosion damage on 7/17/2024



Erosion damage on 8/1/2024

Inspection Photos
Location Name: HSR Sandberg 2-6 Tank Battery
Location ID: 448393



Erosion damage on 7/17/2024



Erosion damage on 8/1/2024