



Jul 31, 2024 10:41:14 AM

## Inspection Photos

Location Name: Dry Creek

Federal 1-14

Location ID: 107-06140

REM #19966

Inspection Date: 7/31/2024

Looking mostly north, downstream. Area of former Flare pit. Vegetation in the background of picture is sage creek. The Creek is approximately 90 feet away. Water was present in Sage Creek.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





**Inspection Photos**  
**Location Name: Dry Creek**  
**Federal 1-14**  
**Location ID: 107-06140**  
**REM #19966**  
**Inspection Date: 7/31/2024**

Photo taken looking mostly south. During excavation activities, groundwater was discovered. A sample of groundwater was collected by HRL consulting.

Jul 31, 2024 11:52:17 AM  
40.39607472717762N 107.22235302440822W



**COLORADO**  
**Energy & Carbon Management**  
**Commission**  
Department of Natural Resources





Inspection Photos  
Location Name: Dry Creek  
Federal 1-14  
Location ID: 107-06140  
REM #19966  
Inspection Date: 7/31/2024

Photo of excavation of  
flare pit.

Jul 31, 2024 11:52:21 AM  
40.3960767807439N 107.22233491949737W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





**Inspection Photos**

**Location Name: Dry Creek**

**Federal 1-14**

**Location ID: 107-06140**

**REM #19966**

**Inspection Date: 7/31/2024**

Photo taken looking north  
on the east side of flare  
pit.

Jul 31, 2024 11:52:38 AM  
40.396086419932544N 107.2222660202533W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





**Inspection Photos**  
**Location Name: Dry Creek**  
**Federal 1-14**  
**Location ID: 107-06140**  
**REM #19966**  
**Inspection Date: 7/31/2024**

Photo taken from the east side of former pit, looking west.

Jul 31, 2024 11:52:48 AM  
40.39608038496226N 107.22223014570773W



**COLORADO**  
**Energy & Carbon Management**  
**Commission**  
Department of Natural Resources





Inspection Photos  
Location Name: Dry Creek  
Federal 1-14  
Location ID: 107-06140  
REM #19966  
Inspection Date: 7/31/2024

Photo taken looking  
south at access road on  
the east side of pit.

Jul 31, 2024 11:53:06 AM  
40.395968738012016N 107.22230608575046W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: Dry Creek  
Federal 1-14  
Location ID: 107-06140  
REM #19966  
Inspection Date: 7/31/2024

Looking southwest  
across flare pit.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Inspection Photos**

**Location Name: Dry Creek**

**Federal 1-14**

**Location ID: 107-06140**

**REM #19966**

**Inspection Date: 7/31/2024**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources