



Inspection Photos
Location Name: Dawson Creek
1-25
Location ID: 107-06242
Inspection Date: 7/30/2024

Sign at entry to
location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dawson Creek
1-25
Location ID: 107-06242
Inspection Date: 7/30/2024

Tank Battery



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dawson Creek
1-25
Location ID: 107-06242
Inspection Date: 7/30/2024

Load out.

Jul 30, 2024 1:50:03 PM
40 45017823576927N 107 21364833414555W
36400 County Road 37
Hayden
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dawson Creek
1-25
Location ID: 107-06242
Inspection Date: 7/30/2024

Tank Battery

Jul 30, 2024 1:50:17 PM
40.45027416665107N 107.2137303929776W
36400 County Road 37
Hayden
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dawson Creek
1-25
Location ID: 107-06242
Inspection Date: 7/30/2024

Production Equipment



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dawson Creek
1-25
Location ID: 107-06242
Inspection Date: 7/30/2024

Production Equipment



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dawson Creek
1-25
Location ID: 107-06242
Inspection Date: 7/30/2024

Production Equipment



40.450365068390965N

Jul 30, 2024 1:50:46 PM

107.21388621255755W

36400 County Road 37

Hayden

Routt County,

Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dawson Creek
1-25
Location ID: 107-06242
Inspection Date: 7/30/2024

Combustor



Jul 30, 2024 1:52:07 PM
40.45064070727676N 107.21329922787845W
36400 County Road 37
Hayden
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dawson Creek
1-25
Location ID: 107-06242
Inspection Date: 7/30/2024

Wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources