

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, HYRUP-68S96W/11NESW

Location ID: 312702

Date: 7/30/2024



Location Entrance – Photo #02453



Wellhead – Photo #02456



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, HYRUP-68S96W/11NESW

Location ID: 312702

Date: 7/30/2024



Separator – Photo #02454



Tank Battery – Photo #02455



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, HYRUP-68S96W/11NESW

Location ID: 312702

Date: 7/30/2024



**Weeds – Photo #02457**