

Inspection Photos

Location Name: CAERUS PICEANCE LLC, HYRUP-68S96W/12SWSW

Location ID: 312698

Date: 7/30/2024



Jul 30, 2024 at 13:12:25

Location Entrance – Photo #02489



Jul 30, 2024 at 13:12:51

Wellhead – Photo #02490

Inspection Photos

Location Name: CAERUS PICEANCE LLC, HYRUP-68S96W/12SWWSW

Location ID: 312698

Date: 7/30/2024



Unsecured Separator – Photo #02492



Tank Battery – Photo #02491

Inspection Photos

Location Name: CAERUS PICEANCE LLC, HYRUP-68S96W/12SWSW

Location ID: 312698

Date: 7/30/2024



Insufficient Erosion Control/Rill Erosion – Photo #02493



Insufficient Erosion Control/Rill Erosion – Photo #02494