

Operator: Highpoint

Location Name: Randall Creek 6-19H

Loc ID: 418462

Inspection: 696301017



Randall Creek 6-19H
22 Jul 2024, 12:24:43 PM

Exhibit A



Exhibit B

CA: All Tanks - NFPA Label has Faded no longer visible. See photos. Install sign to comply with Rule 210.d.

CA Resolution: Operator has provided photo evidence to show that the appropriate labels have now been installed to comply with the 600 series.