

# Reclamation and Stormwater Inspection

Date: 07/25/2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP -  
47120

Location ID: 305848

Inspection Document #: 708201439

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Warner 4-18  
Location ID: 305848



**Photo 1.** Undesirable vegetation around the wellhead appears to have been managed for.



Inspection Photos  
Location Name: Warner 4-18  
Location ID: 305848



**Photo 2.** Subsidence around flowline potholes appears to have been backfilled and leveled.



Inspection Photos  
Location Name: Warner 4-18  
Location ID: 305848



**Photo 3.** Subsidence around flowline potholes appears to have been backfilled and leveled.