

Final Reclamation and Stormwater Inspection

Date: 07/25/204

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 318959

Inspection Document #: 708201441

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Perry #1
Location ID: 318959



Photo 1. Former well location has evidence of subsidence and rock debris throughout.



Photo 2. Facing east near the well location, along the former access road. The access road does not appear to have been contoured and/or graded to reflect adjacent topography.

Inspection Photos
Location Name: Perry #1
Location ID: 318959



Photo 3. Facing west along the former access road, near the entrance off of Beech St. The access road does not appear to have been contoured and/or graded to reflect adjacent topography.

Inspection Photos
Location Name: Perry #1
Location ID: 318959



Photo 4. Facing east along the former access road, near the entrance off of Beech St. See comments in Photo 3.

Inspection Photos
Location Name: Perry #1
Location ID: 318959



Photo 5. Facing east along the former access road, near the entrance off of Beech St. See comments in Photo 3