

Final Reclamation and Stormwater Inspection

Date: 461075

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 461075

Inspection Document #: 708201442

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Photo 1. Southwest corner of former tank battery. Undesirable vegetation (Kochia, CO List C Noxious Weed-Cheatgrass) were observed throughout.

Inspection Photos
Location Name: Perry 1 TB
Location ID: 461075



Photo 2. Southeast corner of the former tank battery; see comments in Photo 1.



Photo 3. The northeastern portion of the former entrance of the tank battery appears to have been paved over.

Inspection Photos
Location Name: Perry 1 TB
Location ID: 461075



Photo 4. Taken near the northern portion of the former tank battery; see comments in Photo 1.

Inspection Photos
Location Name: Perry 1 TB
Location ID: 461075



Photo 5. Reference area photo taken south of the former tank battery location.