

# Final Reclamation and Stormwater Inspection

Date: 07/25/2024

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 441850

Inspection Document #: 708201443

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Drake 01N-65W-26  
Location ID: 441850



**Photo 1.** Facing north from the center of the location. Colorado List C Noxious Weed (field bindweed) was observed throughout the disturbance area.

Inspection Photos  
Location Name: Drake 01N-65W-26  
Location ID: 441850



**Photo 2.** Facing east from the center of the location; see comments in Photo 1.

Inspection Photos  
Location Name: Drake 01N-65W-26  
Location ID: 441850



**Photo 3.** Facing south from the center of the location; see comments in Photo 1.

Inspection Photos  
Location Name: Drake 01N-65W-26  
Location ID: 441850



**Photo 4.** Facing west from the center of the location; see comments in Photo 1.

Inspection Photos  
Location Name: Drake 01N-65W-26  
Location ID: 441850



**Photo 5.** Reference area photo taken west of the abandoned location. Photo illustrates the absence of field bindweed in adjacent areas.