

## Inspection Photos

Operator: PARADOX UPSTREAM LLC - 10453

Location Name: HC BRADY #30-21-45-14

Location ID: 316870 API #: 05-113-06223

Inspection Date: 7/30/2024 Inspection Doc#: 693807570



Wellhead with fencing



Location overview

## Inspection Photos

**Operator: PARADOX UPSTREAM LLC - 10453**

**Location Name: HC BRADY #30-21-45-14**

**Location ID: 316870 API #: 05-113-06223**

**Inspection Date: 7/30/2024 Inspection Doc#: 693807570**



**Separator and Meter housing.**



**Tank Battery**

**Located on Location ID# 316859**





## Inspection Photos

Operator: PARADOX UPSTREAM LLC - 10453

Location Name: HC BRADY #30-21-45-14

Location ID: 316870 API #: 05-113-06223

Inspection Date: 7/30/2024 Inspection Doc#: 693807570



FLIR video of leaking tubing valve stem.

